

Federal Communications Commission

**Before the
Federal Communications Commission
Washington, D.C. 20554**

In the Matter of)	
)	
AAT Communications Corporation)	File No. EB-04-PO-050
ASR# 1201911)	
Emmett, Idaho)	NOV No. N20043292005

NOTICE OF VIOLATION

Released: April 20, 2004

By the Resident Agent, Portland Office, Enforcement Bureau:

1. This is a Notice of Violation ("Notice") issued pursuant to Section 1.89 of the Commission's Rules,¹ to AAT Communications Corporation.

2. On April 11, 2004, the FCC Portland Resident Agent Office received a copy of a Notice to Airmen ("NOTAM") referred from the Federal Aviation Administration ("FAA") in Boise, Idaho. The investigation from this Office revealed that since February 13, 2004, the FAA has issued five consecutive NOTAMs (BOI D 02/060, BOI D 02/123, BOI D 03/046, BOI D 03/094, and BOI D 04/047) to a registered antenna structure located in Emmett, Idaho due to problems with the antenna structure's lighting equipment. FCC records show that the referenced antenna structure was registered to AAT Communications Corporation, under Antenna Structure Registration Number 1201911. The geographic coordinates for this antenna site are 43°51'42" north latitude and 116°31'48" west longitude.

- a. 47 C.F.R. § 17.56(a): "Replacing or repairing of lights, automatic indicators or automatic control alarm systems shall be accomplished as soon as practicable."

Because of hazards to air navigation due to the proximity of the antenna structure to the Emmett Municipal Airport, which is approximately 4,400 feet away, AAT Communications Corporation must diligently investigate the ongoing problem and resolve the light failure.

3. Pursuant to Section 308(b) of the Communications Act of 1934, as amended,² and Section 1.89 of the Commission's Rules, AAT Communications Corporation, must submit a written

¹ 47 C.F.R. § 1.89.

² 47 U.S.C. § 308(b).

Federal Communications Commission

statement concerning this matter within 20 days of release of this Notice. The response must fully explain the violation, must contain a statement of the specific action taken to correct the violation and preclude recurrence, and should include a time line for completion of pending corrective action. The response must be complete in itself and signed by a principal or officer of the licensee. All replies and documentation sent in response to this Notice should be marked with the File No. and NOV No. specified above, and mailed to the following address:

Federal Communications Commission
Portland Resident Agent Office
P.O. Box 61469
Vancouver, WA 98666-1469

4. This Notice shall be sent to AAT Communications Corporation, 517 Route One South, Suite 5000, Iselin, NJ 08830.

5. The Privacy Act of 1974³ requires that we advise you that the Commission will use all relevant material information before it, including any information disclosed in your reply, to determine what, if any, enforcement action is required to ensure compliance. Any false statement made knowingly and willfully in reply to this Notice is punishable by fine or imprisonment under Title 18 of the U.S. Code.⁴

FEDERAL COMMUNICATIONS COMMISSION

Binh Nguyen
Resident Agent
Portland Office

Cc: Larry F. Schutz, Vice President-Engineering
AAT Communications Corporation
12444 Powerscourt Drive, Suite 140
St. Louis, MO 63131

³ P.L. 93-579, 5 U.S.C. § 552a(e)(3).

⁴ 18 U.S.C. § 1001 *et seq.*